HOW TO GET BACK THE POWER ANALYZER 2 CALIBRATION.


(or read the page 10-11)

Power Analyzer 2 / Energy Meter 2

Equipments Required

- A PC with COM port using "Terminal by Br@y++" program (https://sites.google.com/site/terminalbpp/)
- Serial cable to connect to PC.
- Download the Supporting Documents for Power Analyzer2(https://drive.google.com/folderview?id=0BxdLxDCD6HiddTRhWGhxUGh6Sk0&usp=sharing)
- Note: You can skip STEP1-4 then go to STEP5-12 (For immediate calibration).

1.Download Terminal by Br@y++



Download & Links

Download new version of the Terminal software - version 1.93b 20141030



Click to download

(https://sites.google.com/site/terminalbpp/)

2. Construct this Serial cable to connect to PC.




Figure 4. Interface wiring to a PC RS-232 COM port is surprisingly simple. Measurements can be displayed on a PC using terminal programs such as Terminal by Br@y++ (see section 5.2). If you can write your own PC app, then, you can customize your own display and functions. A sample program written in VB.net can be downloaded for free from the corresponding product page of this kit @ e-gizmo.com.

3. Set Communication

In Terminal, Settings

BAUDRATE: 9600


DATA BITS – 8

PARITY - NONE

STOP BITS - 1


HANDSHAKING - RTS/CTS

Select the COM# then connect.



4. Power ON the Power Analyzer


- The data should start streaming in.
- If no data is displayed, try typing: \$02M1\$03



The Click SEND.


5. Power OFF the Power Analyzer

6. Remove the OFFSET CALIBRATION JUMPER and UNPLUG/DISCONNECT ANY LOAD in the P1 AC OUT side.



WITHOUT JUMPER!!!


- 7. Reapply AC POWER. Open/Run the Visual Basic Sample program.
- 8. Find the portion in the displayed measurements that indicates VOLT RMS. Make sure it displays a value of less than 5 VAC.



WITHOUT JUMPER!!!


- 9. Close/Stop the Visual Basic sample.
- 10. OPEN THE TERMINAL and CONNECT AGAIN.
- 11. Type \$020\$03 at the terminal transmit window and then click SEND.

This will initiate the offset calibration procedure. Wait until the Power Analyzer completes the procedure. This should take less than 30 seconds.




AFTER 30 SECONDS.

12. POWER OFF the Power Analyzer and REINSTALL THE JUMPER REMOVED.



CHECK AGAIN THE VALUE SHOULD BE LIKE THIS.



Done :-)